

INCIDENT REPORT FORM

TO: GENERAL SUPERVISOR

CC: FACTORY MANAGER
SAFETY DIRECTOR
SUPERINTENDENT

SUBJECT: Triethanolamine Chem-Mill Solution - Tanker over Flow

AFFECTED SHOP: A-3190 DATE: 10/17/89

AFFECTED AIRPLANE: _____ TIME: 8:30 AM.


1. WHAT OCCURRED: Plumbers were Pumping the Chem-Mill Solution into a Tanker Truck which was Too Small (2000 gal Cap) and The Solution ran over on to the Floor.

2. ACTION TAKEN: Maintenance was Pumping the Solution so they radioed for a Vacuum Pump. They also Transferred some of the Solution back into the Chem-Mill holding Tank # 9. After that the Tanker was sent on its way. IT returned 2 hours later to pick-up

3. AFFECT ON SCHEDULES: Remainder of spent Chemicals.

4. WOULD THE CONDITION BE SIMILAR ON OTHER AIRPLANES? _____

5. THIS INFORMATION HAS BEEN OBTAINED BY: _____


SIGNATURE OF SUPERVISOR